

Service Bulletin
B1180047A-07

Action required:	Not sold
Only if encountered	
X Information only	

SB, Firmware update m/2019, Automower® 105, Gardena R38Li, R40Li, R45i, R50Li, R70Li, R80Li, McCulloch ROB R600, ROB R800, ROB R1000, Flymo 1200R, 2018-12

Affected models

Model	PNC	Serial	Serial Range	
		Start	End	
Automower® 105		160100001	184999999	
Gardena R38Li		160100001	184999999	
Gardena R40Li		160100001	184999999	
Gardena R45Li		160100001	184999999	
Gardena R50Li		160100001	184999999	
Gardena R70Li		160100001	184999999	
Gardena R80Li		160100001	184999999	
McCulloch ROB R600		160100001	184999999	
McCulloch ROB R800		160100001	184999999	
McCulloch ROB R1000		160100001	184999999	
McCulloch Flymo 1200R		160100001	194599999	

Affected market(s)

All.

Description

New firmware has been released, firmware package 5825856-08A. The firmware package contains the following changes:

- Extended foot detection (added to comply with future iterations of the robotic standard regulation, EN 50636-2-107):
 - Added extended functionality to identify if the mower runs over a foot or similar objects when reversing
 - When an object is identified the product will stop its blade motor and try to move away from the identified object
 - Having moved away from the object the mower will start cutting again after 25 seconds.
- Several minor firmware improvements (not described in detail in this SB).

English Page 1 of 2



	B1180047A-07
Action required:	
Sold	Not sold
Only if encountered Information only	

Service Bulletin

Dealers are recommended to update the software:

- As a normal part of PDI prior to sales of a new product
- In case of a customer complaint on any of the issues described above
- At latest at next service.

Revision History

_			<u> </u>	
	Rev.	Date	Order id.	Description
	Α	2018-12	SB-3673	Created

English Page 2 of 2