

Service	Bul	letin
R118	በበ31	ΙΔ_11

Action required:	Not sold
Only if encountered	
X Information only	

SB, Premature Piston Pin Wear, M125-85F, M125-85FH, M115-77TC, M125-97TC, M125-97T, 2018-06

Affected models

Model	PNC	Serial Range	
		Start	End
M125-85F	967 29 54-01	20181400022	20181600020
M125-85FH	967 18 69-01	20181500001	20181600033
M115-77TC	960 51 00-59	010818*****	062518*****
M115-77TC Hydro	960 51 01-61	010818*****	062518*****
M125-97TC	960 51 01-49	010818*****	062518*****
M125-97T	960 41 03-81	010818*****	062518*****

Affected market(s)

All.

Description

Briggs and Stratton have informed that they have received reports of premature piston pin wear on subject engines.

Affected engine model is M21 single cylinder.

Affected serial number on engines is: 180106xxxxxxx through 180201xxxxxxx.

Attached to this bulletin is a copy of the Service Bulletin from Briggs & Stratton outlining the information. Translated versions can be found in B&S network.

Action

	Product sold to end user	Residual inventory not yet sold	
What is required:	Service is not applicable	ervice is not applicable Service is not applicable	
When to do:	Information only	Information only	
What to do:	Contact closest Briggs & Stratton distributor		
How to do:	N/A		

Additional information

Briggs and Stratton Service Bulletin, Issue No: CSB-1046, Issue date: June 2018.

English Page 1 of 2



Service	Bul	letin
B118	0031	A-11

Action required:	Not sold
Only if encountered	
X Information only	

Revision History

Rev.	Date	Order id.	Description
Α	2018-07	SB-2797	Created

English Page 2 of 2



BRIGGS & STRATTON CORPORATION

SERVICE BULLETIN

1

TO: ALL AUTHORIZED CENTRAL SERVICE DISTRIBUTORS

BULLETIN: CSB -1046

DATE: JUNE 2018

SUBJECT: PREMATURE PISTON PIN WEAR

MODEL: 210000 SINGLE CYLINDER OHV

SERIAL NUMBER: 180106XXXXXXXX THROUGH 180201XXXXXXXX

□ - ACTION REQUIRED☑ - IF ENCOUNTERED□ - INFORMATION ONLY
☑ - ENGINE
T - FOLIPMENT

☐ - BOTH

CONDITION:

We have received some reports of premature piston pin wear on subject engines. Upon examination of returned parts from the field, we have concluded that improper plating of the pins allowed for premature and excessive wear.

CORRECTION:

The warranty rate remains quite low at the present time and we will continue to monitor warranty claims and update this bulletin should any additional action become necessary. Briggs & Stratton has decided to provide an additional year of consumer warranty coverage attributed to piston pin failures for engines within the subject model/serial number range.

WARRANTY:

This bulletin extends consumer warranty term to 3 years for piston pin related failures on engines within subject serial number range. All other normal warranty guidelines apply. For short-block and engine replacements, pre-authorization is required through the dealer's source of supply. Upon approval, order and install the appropriate replacement and file a Briggs & Stratton warranty claim accordingly.

When filing a warranty claim, please select the following in the *Conditions* section of the claim to help ensure appropriate handling of the claim:

Equipment Type: Make the appropriate selection from the drop down menu

Key Part Identification Category: Piston/Rings & Connecting Rod

Key Part Identification Code: **Piston Pin** Condition Code: **SP (Special Program)**

BRIGGS & STRATTON CORPORATION

Global Support Group