

<input type="checkbox"/>	Intervento richiesto:	<input type="checkbox"/> Venduto	<input type="checkbox"/> Non venduto
<input type="checkbox"/>	Solo se è stato riscontrato il problema		
<input checked="" type="checkbox"/>	Solo informazioni		

## SB, Usura prematura del perno del pistone, M125-85F, M125-85FH, M115-77TC, M125-97TC, M125-97T, 2018-06

### Modelli interessati

Modello	PNC	Intervallo di numeri di serie	
		Inizio	Fine
M125-85F	967 29 54-01	20181400022	20181600020
M125-85FH	967 18 69-01	20181500001	20181600033
M115-77TC	960 51 00-59	010818*****	062518*****
M115-77TC Hydro	960 51 01-61	010818*****	062518*****
M125-97TC	960 51 01-49	010818*****	062518*****
M125-97T	960 41 03-81	010818*****	062518*****

### Mercati interessati

Tutti.

### Descrizione

Briggs & Stratton ha segnalato di aver ricevuto rapporti sull'usura prematura del perno del pistone sui motori in oggetto.

Il modello di motore interessato è l'M21 con un solo cilindro.

Il numero di serie sui motori interessati è: Da 180106xxxxxxx a 180201xxxxxxx.

Una copia del bollettino di manutenzione di Briggs & Stratton che contiene le informazioni e le azioni necessarie è allegata a questo bollettino. Le versioni tradotte si trovano sulla rete B&S.

### Azione

	Prodotto venduto agli utenti finali	Scorte residue non ancora vendute
<b>Cosa è obbligatorio</b>	L'assistenza non è applicabile	L'assistenza non è applicabile
<b>Quando è necessario effettuare l'intervento</b>	Solo informazioni	Solo informazioni
<b>Cosa fare:</b>	Contattare il distributore Briggs & Stratton più vicino	
<b>In che modo intervenire:</b>	N/A	

<input type="checkbox"/>	Intervento richiesto:	<input type="checkbox"/>	Venduto	<input type="checkbox"/>	Non venduto
<input type="checkbox"/>	Solo se è stato riscontrato il problema				
<input checked="" type="checkbox"/>	Solo informazioni				

**Informazioni aggiuntive**

Bollettino di manutenzione Briggs e Stratton, numero di pubblicazione: **CSB-1046**, data di pubblicazione: Giugno 2018.

**Cronologia delle revisioni**

<b>Rev.</b>	<b>Data</b>	<b>ID ordine</b>	<b>Descrizione</b>
A	2018-07	SB-2797	Creato il



# SERVICE BULLETIN



**TO:** ALL AUTHORIZED CENTRAL SERVICE DISTRIBUTORS  
**BULLETIN:** CSB -1046  
**DATE:** JUNE 2018  
**SUBJECT:** PREMATURE PISTON PIN WEAR  
**MODEL:** 210000 SINGLE CYLINDER OHV  
**SERIAL NUMBER:** 180106XXXXXX THROUGH 180201XXXXXX

<input type="checkbox"/>	- ACTION REQUIRED
<input checked="" type="checkbox"/>	- IF ENCOUNTERED
<input type="checkbox"/>	- INFORMATION ONLY

<input checked="" type="checkbox"/>	- ENGINE
<input type="checkbox"/>	- EQUIPMENT
<input type="checkbox"/>	- BOTH

**CONDITION:**

We have received some reports of premature piston pin wear on subject engines. Upon examination of returned parts from the field, we have concluded that improper plating of the pins allowed for premature and excessive wear.

**CORRECTION:**

The warranty rate remains quite low at the present time and we will continue to monitor warranty claims and update this bulletin should any additional action become necessary. Briggs & Stratton has decided to provide an additional year of consumer warranty coverage attributed to piston pin failures for engines within the subject model/serial number range.

**WARRANTY:**

This bulletin extends consumer warranty term to 3 years for piston pin related failures on engines within subject serial number range. All other normal warranty guidelines apply. For short-block and engine replacements, pre-authorization is required through the dealer's source of supply. Upon approval, order and install the appropriate replacement and file a Briggs & Stratton warranty claim accordingly.

When filing a warranty claim, please select the following in the *Conditions* section of the claim to help ensure appropriate handling of the claim:

- Equipment Type: **Make the appropriate selection from the drop down menu**
- Key Part Identification Category: **Piston/Rings & Connecting Rod**
- Key Part Identification Code: **Piston Pin**
- Condition Code: **SP (Special Program)**

**BRIGGS & STRATTON CORPORATION**  
Global Support Group