

SB, Software Bundle 5939789-06A has been released, McCulloch P0.1, 2021-12

Affected models

Model	Serial Range
ROB S400	All
ROB S600	All
ROB S500	All
ROB S800	All

Affected markets

All.

Description

A new version of mower software has been released for the affected models (see above).

This includes the following changes:

- Charging current supervision
 - o Check if charging current is as expected. If this is not the case, the mower will dock again (up to 8 times). If still not as expected, the mower will display error 30 (charging system error).
- Defining starting point in start-up sequence.
- Guide calibration available in installation menu.
- Support for ZoneProtect.
- Schedule wizard is adapted for 1A PSU.
- Support for new security code handling at los PIN code (256byte).
- Bug fixes.

It is strongly recommended to update the mowers at next service!

Warranty reporting information

Nothing in this SB can be subject to warranty claims. Warranty claims will not be accepted.

Revision History

Rev.	Date	Order id.	Description
A	2021-12	00016036	Created