

SB, Lawnmower, McCulloch Facelift series, Cutting height adjustment, 2010-10

Products involved:

Model	PNC
M46-450CD	9666816-01
M46-450CMD	9667117-01
M46-500CD	9666442-01
M46-500CD	9666442-02
M46-135CMD	9667118-01
M46-500CMDW	9666443-01
M46-450CMDWA	9666445-01
M46-550CMDW	9666908-01
M46-135CMDWA	9665319-01
M51-550CMD	9666705-01
M51-550CMD	9666705-02
M51-650CMD	9666536-01
M51-135CMD	9666448-01
M51-160CMD	9667116-01
M53-190CMD	9667155-01
M51-550CMDW	9666537-01
M 51-625CMDW	9666869-01
M51-160CMDWA	9665320-01

Due to problems with height adjustment on Facelift lawnmowers with 46cm and 51 cm deck, we have developed a new height adjuster for better performance.

This will be screwed on to chassis. The chassis was before easily bent in the fixing point of the height adjuster. The new solution prevents this. Also it will keep the height positions in a better way.

**Service kit:**

5775456-01, Height adjustment kit, Facelift mowers with 46cm and 51cm deck

Includes following articles:

1 pcs, 5765550-01 Index plate

1 pcs, 5444525-01 Lever

1 pcs, 5312072-70 Screw

1 pcs, 5312052-13 Nut

5765550-01, index plate, will replace old index plate, 544 45 22-01.