

SB, Electrical harness and battery, M95-66x, M105-77X, M105-77XC, 2014-05

Affected models

Model	Product number
M95-66X	960 21 00-23
M105-77X	960 21 00-28
M105-77XC	960 21 00-29

Affected serial number(s)

Production up to and including year of manufacture 2013.

Problem description

A new battery harness and new connectors has been introduced and below table show what parts are needed for each service.

Parts information

New part no.	Part description	Excl. part no.
586457801	Repair kit	532437070
586457802	Repair kit	532428477
586457803	Repair kit	532442241

586457801 includes:

- Instruction sheet
- Harness to battery adapters
- Battery

586457802 includes:

- Instruction sheet
- Harness to battery adapters
- Harness

586457803 includes:

- Instruction sheet
- Harness to battery adapters
- Harness