

SB, Firmware update m/2020, Automower® 105, Gardena R38Li, R40Li, R45Li, R50Li, R70Li, R80Li, McCulloch ROB R600, ROB R800, ROB R1000, Flymo 1200R, 2020-01

Affected models

Model	PNC	Serial Range	
		Start	End
Automower® 105	All	160100001	195199999
Gardena R38Li	All	160100001	195199999
Gardena R40Li	All	160100001	195199999
Gardena R45Li	All	160100001	195199999
Gardena R50Li	All	160100001	195199999
Gardena R70Li	All	160100001	195199999
Gardena R80Li	All	160100001	195199999
McCulloch ROB R600	All	160400001	195199999
McCulloch ROB R800	All	160400001	195199999
McCulloch ROB R1000	All	160400001	195199999
Flymo 1200R	All	160100001	195199999

Affected markets

All.

Description

New firmware has been released: firmware package 5825856-09A. The firmware package contains the following changes:

- Several minor bugfixes and improvements.

Revision History

Rev.	Date	Order id.	Description
A	2020-01	SB-5170	Created