

Service Bulletin B1220019A-07

Action required	
Information only	Χ

SB, No additional grease tube in box, 122HD, 322HD, 522HD etc, 2022-05

Affected models

Model	PNC	Serial Range	
		Start	End
122HD45	966532301	20221800001	20222600001
122HD60	966532401		
322HD60	967658902		
322HD60	967658901		
522HD60S	967658803		
522HD60S	967658801		
522HD60X	967658701		
522HDR60S	967658502		
522HDR60X	967658301		
522HDR75X	967658401		
522HSR75X	967659001		
CHTZ600	967659501		
CHTZ600R	967659401		
Ergolite 6028	966693401		
HTZ750	967659601		
Superlite 4528	966693301		

Affected markets

All.

Description

Due to shortage of certain lubricant articles, hedge trimmers will be delivered for a limited time without the additional grease tube in box. Hence, the Product overview in the Operator's manual is adjusted with tape patches to cover "22. Tube of grease". Note that the hedge trimmer gearbox is still filled with correct grease from factory.

We apologize for the inconvenience.

Red arrows in the picture below show the tape patches covering "22. Tube of grease".


English Page 1 of 2



Service Bulletin B1220019A-07

Action required Information only X

Product overview



- 1. Operator's manual
- 2. Rear handle
- 3. Throttle trigger lockout
- 4. Fuel tank cap
- Choke control
- 6. Front handle
- 7. Blade and blade guard
- 8. Transport guard
- 9. Air filter cover
- 10. Air purge bulb
- 11. Fuel tank
- 12. Handle lock
- 13. Throttle trigger
- 14. Spark plug cap and spark plug
- 15. Cylinder cover

- 16. Starter rope handle
- 17. Stop switch
- 18. Grease nipple
- 19. Gear housing
- 20. Hand guard 21. Combination wrench
- 23. Blade tip protection

Product description

The product is a hedge trimmer with a combustion engine.

Intended use

Use the product to cut branches and twigs. Do not use the product for other tasks.

Revision History

Rev.	Date	Order id.	Description
Α	2022-05	00020139	Created

English Page 2 of 2