

SB, 2022-Version of Robotic Upgrade Tool has been released (Windows and macOS), P0.1, P0.2, P15, P1, 2021-12

Affected models

Model	PNC	Serial Range	
		Start	End
ROB R600 – R1000	All	2016	All
ROB S400 – S800	All	All	All

Affected markets

All.

Description

Changes in Software Version 1.2.21315.3:

Who will be prompted by the system to update and who will not:

- Windows OS
 - o Update Tool 1.0 → no
 - o Update Tool 1.1 → yes
- Mac OS
 - o Will not be prompted

Operating System Requirement

- Windows 10 or later (as before)
- Mac 10.11 or later (10.10 is not supported anymore)

New Functionality

- Handling of 256byte security code with P01 (ROB Sxxx)
- **Support for P1 Mower (ROB Rxxx)**
- Prompt the user when an update is available on macOS (for next update as Version 1.3 and so on)

Improvements

- Desktop Icon gets created after installation + start program (default)
- Several minor bug fixes

Action required

Information only

Action (generally for the Update Tool, like previous SMB)

	Product sold to end user	Residual inventory not yet sold
What is required:	Offer USB cable and screwdriver	No action
When to do:	If requested	
What to do:	Send customer spare parts	
How to do:	Free of charge	

Parts information

New part no.	Part description	Quantity	Old part no.
00057-75.181.02	USB cable	1	-
04067-20.990.02	Torx T20 screwdriver (Gardena branded)	1	-

Warranty reporting information

Warranty is not approved; information only!

Revision History

Rev.	Date	Order id.	Description
A	2021-12	00016092	Created